

KING COUNTY

SITE ID:	Philip Services Co Kent		Cleanup Site ID: 12484		FS ID: 70726415
	Alternate Name(s): Burlington Environmental LLC Kent, Philip Services Co Kent				
LOCATION:	WRIA: 9		Lat/Long: 47.419 -122.238		View Vicinity Map
Address:	20245 77TH AVE S		Township	Range	Section
	KENT	98032-1386	22N	4E	1
					Legislative District: 33
					Congressional District: 9
STATUS:	Cleanup Started		Rank:		View Site Web Page
	Responsible Unit: Northwest	Site Manager: Harrover, Robin D.		Statute: MTCA (RCRA)	
	Is Brownfield?	Has Environmental Covenant?		Is PSI Site?	
	NFA Received?	NFA Date:		NFA Reason:	

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
13126	Philip Services Co Kent	Upland	Ecology-supervised or conducted	Cleanup Started		563035

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received			8/4/1980			Northwest Region
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	5/30/2007	7/3/2007		Ecology	Harrover, Robin D.

AFFECTED MEDIA & CONTAMINANTS:
Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Arsenic	C	C	C			
Benzene	C					
Conventional Contaminants, Organic	C					
Halogenated Pesticides		C	C			
Lead			C			
Mercury			C			
Metals - Other			C			
Non-Halogenated Pesticides		C	C			
Non-Halogenated Solvents	C	C				

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

Other Non-Halogenated Organics		C				
Petroleum-Other	C		C			
Polychlorinated biPhenyls (PCB)		C				
Polynuclear Aromatic Hydrocarbons	C		C			

CleanupSiteDetails2014